

DATA 0841Z 30 DEC 62

SECRET

2	3
3	6

PRIORITY

TO DIRECTOR

FROM [REDACTED]

25X1A

ACTION SA/TCO (1-2-3-4-5-6-7-8)

INFO :


TOR: 1035Z 30 DEC 62

25X1A

IN 60776

25X1A

2528



25X1A

1. [REDACTED]
2. 9R/0-19-6000/195-18-8-2/9L/0-19-6000/192-12-7-2
3. D-19/4/75 DEGREES/HTA-2
4. 2.0
5. FAIR TO GOOD/MEDIUM/GOOD/ SEE PAR. 6.
6. TAKE RECEIVED 2055Z 28 DEC 62 IN COVERED STEEL BOXES.

CONDITION OF TAKE GOOD HOWEVER 9L BOX BADLY BENT ON VALVE SIDE. SHUTTER MALFUNCTION AT FRAME NR 2454. NO EXPOSURE AFTERWARDS EXCEPT DATA CLOCK. APPARENT INTERMITTENT DATA CLOCK MALFUNCTION. FRAME NR 14L INDICATES 0942, FRAME NR 15L INDICATES 1004. FRAME 24L SHOWS 102930. FRAME NR 25L SHOWS 105210. FRAME 14R SHOWS 0942. FRAME 15R INDICATES 1015. FRAME COUNTER REPEATING UP TO THREE TIMES AFTER SHUTTER MALFUNCTION. FILM CREASES EXPOSURES 10-25L, 1268-74-R 1347-51 R, 1378-79 R. IPIR TRANSMITTED 300138Z.

SECRET

GROUP 1
Excluded from automatic
downgrading and
declassification

25X1A

[REDACTED] 2628 (IN 60776)

S E C R E T

PAGE TWO

7. NOT ACCOMPLISHED.

25X1A

NEW SUBJECT: REF [REDACTED]

25X1A

[REDACTED] REPORT ON MSN 3206. ITEM 2 SHOULD READ 9L/0-11-6000/
189-9-10-6-2/9R/0-11-6000/185-4-5-2.

END OF MESSAGE

S E C R E T